

## Annex II

### List of inspection activities for which accreditation has been terminated

(Notification Letter No. HKIAS010-40; Effective date of termination: 19 December 2024)

#### **ETS-Testconsult Limited**

東業德勤測試顧問有限公司

8/F, Block B, Veristrong Industrial Centre, 34-36 Au Pui Wan Street, Fo Tan, New Territories, Hong Kong

香港新界火炭坳背灣街 34-36 號豐盛工業中心 B 座 8 樓

Construction Products 建築產品		
ITEM INSPECTED 檢驗項目	SPECIFIC PROPERTY OR CHARACTERISTIC INSPECTED 特定檢驗特性或特徵	SPECIFICATION, INSPECTION METHOD OR STANDARD 規範、檢驗方法或標準
The accreditation of the following inspection activities has been terminated		
Welding Inspection	Inspection of welding procedure (MMAW, SAW, TIG, MIG, MAG, FCAW)	BS 4870: Part 1: 1981 + Amd. 4322 + Amd. 4730 + Amd. 5161 + Amd. 6293 BS EN 288-3: 1992 + Amd. 9736 + Amd. 10026 Corr. No. 1
	Inspection of welder testing (MMAW, SAW, TIG, MIG, MAG, FCAW)	BS 4871: Part 1: 1982 + Amd. 4732 + Amd. 5697 BS EN 287-1: 1992 + Amd. 9665 + Amd. 9804 + Amd. 10009 Corr. No. 1 ISO 9606-1: 1994 + A1: 1998

## Annex II

### List of inspection activities for which accreditation has been terminated

(Notification Letter No. HKIAS010-39; Effective date of termination: 15 December 2023)

#### **ETS-Testconsult Limited**

東業德勤測試顧問有限公司

8/F, Block B, Veristrong Industrial Centre, 34-36 Au Pui Wan Street, Fo Tan, New Territories, Hong Kong

香港新界火炭坳背灣街 34-36 號豐盛工業中心 B 座 8 樓

Construction Products 建築產品		
ITEM INSPECTED 檢驗項目	SPECIFIC PROPERTY OR CHARACTERISTIC INSPECTED 特定檢驗特性或特徵	SPECIFICATION, INSPECTION METHOD OR STANDARD 規範、檢驗方法或標準
The accreditation of the following inspection activities has been terminated		
Welding Inspection	Inspection of welding procedure (MMAW, SAW, TIG, MIG, MAG, FCAW)	BS EN ISO 15609-1: 2004 BS EN ISO 15609-1: 2019