

**Annex II**

**List of inspection activities for which accreditation has been terminated**

(Notification Letter No. HKIAS026-24; Effective date of termination: 16 December 2024)

**The Lab (Asia) Limited**

22 San Hi Tsuen Street, Ping Shan, Yuen Long, New Territories  
新界元朗屏山新起村街 22 號

Construction Products 建築產品		
ITEM INSPECTED 檢驗項目	SPECIFIC PROPERTY OR CHARACTERISTIC INSPECTED 特定檢驗特性或特徵	SPECIFICATION, INSPECTION METHOD OR STANDARD 規範、檢驗方法或標準
The accreditation of the following inspection activities has been terminated		
Welding Inspection	Inspection of welder testing (MMAW, TIG, MIG, MAG, FCAW, SAW)	BS EN 287-1: 2004 BS EN ISO 9606-1: 2013 ISO 9606-1: 1994 + A1: 1998
	Inspection of arc stud welding procedure	BS EN ISO 14555: 2006

## Annex II

### List of inspection activities for which accreditation has been terminated

(Notification Letter No. HKIAS026-21; Effective date of termination: 14 December 2023)

#### **The Lab (Asia) Limited**

22 San Hi Tsuen Street, Ping Shan, Yuen Long, New Territories

新界元朗屏山新起村街 22 號

Construction Products 建築產品		
ITEM INSPECTED 檢驗項目	SPECIFIC PROPERTY OR CHARACTERISTIC INSPECTED 特定檢驗特性或特徵	SPECIFICATION, INSPECTION METHOD OR STANDARD 規範、檢驗方法或標準
The accreditation of the following inspection activities has been terminated		
Welding Inspection	Inspection of welding procedure (MMAW, TIG, MIG, MAG, FCAW, SAW)  Inspection of welder testing (MMAW, TIG, MIG, MAG, FCAW, SAW)	BS EN ISO 15609-1: 2004 BS EN ISO 15609-1: 2019 in conjunction with the following inspection method(s): BS 4870: Part 1: 1981 + Amd. 6293 BS EN 288-3: 1992 + Amd. 9736 + Amd. 10026 Corr. No. 1  BS 4871: Part 1: 1982 + Amd. 5697 BS 4872: Part 1: 1982 + Amd. 4640 BS EN 287-1: 1992 + Amd. 9665 + Amd. 10009 Corr. No. 1