



Architectural Services Department - Indoor Air Quality Inspection Unit

建築署 – 室內空氣質素檢驗組

ADDRESS : 31 Floor, Queensway Government Offices, 66, Queensway, Hong Kong
地址 香港金鐘道 66 號金鐘道政府合署 31 樓

ENQUIRY : Mr PUN Kai-kwong, Chief Technical Officer (BS)/Works
查詢 潘啟光先生，總技術主任(屋宇裝備)/工程

TELEPHONE : 2867 8093
電話

FAX : 2596 0361
傳真

E-MAIL : punkk@archsd.gov.hk
電郵

WEBSITE ADDRESS : <http://www.archsd.gov.hk>
網址

CLIENTELE : Government departments, normally not available for public testing
服務對象 通常只服務政府部門



Scope of Accreditation
Registration No. HKIAS 020
Page 1 of 3
Issue Date: 10 September 2018
Ref: HKIAS020-17

Architectural Services Department - Indoor Air Quality Inspection Unit

建築署 - 室內空氣質素檢驗組

ADDRESS

地址

: 31 Floor, Queensway Government Offices, 66, Queensway,
Hong Kong
香港金鐘道 66 號金鐘道政府合署 31 樓

TYPE OF INSPECTION BODY

檢驗機構類別

: C : Provides in-house inspection service to Architectural
Service Department 為建築署提供內部檢驗服務

ACCREDITED INSPECTION

FIELD

認可檢驗領域

: Indoor Air Quality Inspection 室內空氣質素檢驗

Architectural Services Department - Indoor Air Quality Inspection Unit
 建築署 - 室內空氣質素檢驗組

31 Floor, Queensway Government Offices, 66, Queensway, Hong Kong
 香港金鐘道 66 號金鐘道政府合署 31 樓

Indoor Air Quality Inspection 室內空氣質素檢驗		
ITEM INSPECTED 檢驗項目	SPECIFIC PROPERTY OR CHARACTERISTIC INSPECTED 特定檢驗特性或特徵	SPECIFIC INSPECTION METHOD OR STANDARD 特定檢驗方法或標準
Indoor Air Quality	On-site measurement of :	A Guide on Indoor Air Quality Certification Scheme for Offices and Public Places, The Government of the HKSAR, Indoor Air Quality Management Group, September 2003
	- Temperature	Annex 3 (a), as documented in IAQIU-IM-01 (Temperature sensor ; thermistor) .vs.
	- Relative Humidity	Annex 3 (a), as documented in IAQIU-IM-02 (Humidity sensor capacitive measurement principle) .vs.
	- Air Movement	Annex 3 (a), as documented in IAQIU-IM-03 (Hot wire velocity probe) .vs.
	- Carbon Dioxide	Annex 3 (b), as documented in IAQIU-IM-04 (Non-dispersive infrared NDIR) .vs.
	- Carbon Monoxide	Annex 3 (b), as documented in IAQIU-IM-05 (Electrochemical sensor) .vs.
	- Respirable Suspended Particulate	Annex 3 (g), as documented in IAQIU-IM-06 (Light scattering laser diode) .vs.
	- Total Volatile Organic Compound	Annex 3 (h), as documented in IAQIU-IM-10 (Photo-ionization sensor) .vs.
	- Radon	Annex 3 (c), as documented in IAQIU-IM-11 (Electrostatic collection of alpha-emitters with spectral analysis) .vs.
	- Ozone	Annex 3 (f), as documented in IAQIU-IM-08 (UV adsorption photometric analyser) .vs.
	On-site sampling of :	
	- Airborne Bacteria	Annex 3 (i), as documented in IAQIU-IM-12 (Single stage impactor) .vs.
	- Formaldehyde	Annex 3 (d), as documented in IAQIU-IM-09 (Passive sampler) .vs.
- Nitrogen Dioxide	Annex 3 (e), as documented in IAQIU-IM-07 (Passive sampler) .vs.	
Walkthrough Inspection	Clause 11 .vs.	
IAQ Compliance Assessment	Clause 13 to Clause 28 .vs.	



Scope of Accreditation
Registration No. HKIAS 020
Page 3 of 3
Issue Date: 10 September 2018
Ref: HKIAS020-17

Architectural Services Department - Indoor Air Quality Inspection Unit

建築署 - 室內空氣質素檢驗組

Summary of Voluntary Suspension

.vs. denotes inspection(s) for which the accreditation has been voluntarily suspended with effect from 8 September 2018 (Notification Letter no. HKIAS020-17).