

Annex III

List of inspection activities for which accreditation has been terminated

(Notification letter No.: HKIAS007-75; Effective Date of Termination: 28 November 2024)

Castco Testing Centre Ltd.

佳力高試驗中心有限公司

1/F, Sun Ling Plaza, 30 On Kui Street, On Lok Tsuen, Fanling, New Territories, Hong Kong

香港新界粉嶺安樂村安居街 30 號新寧中心 1 樓

Indoor Air Quality Inspection 室內空氣質素檢驗		
ITEM INSPECTED 檢驗項目	SPECIFIC PROPERTY OR CHARACTERISTIC INSPECTED 特定檢驗特性或特徵	SPECIFIC INSPECTION METHOD OR STANDARD 特定檢驗方法或標準
Accreditation of the following inspection activities has been terminated		
Indoor Air Quality	On-site measurement of : - Temperature - Relative Humidity - Air Movement - Carbon Dioxide - Carbon Monoxide - Respirable Suspended Particulate - Ozone - Total Volatile Organic Compounds - Radon - Nitrogen Dioxide	A Guide on Indoor Air Quality Certification Scheme for Offices and Public Places, The Government of the HKSAR, Indoor Air Quality Management Group, September 2003 Annex 3 (a), as documented in INS-IAQ-SOP01-TEMP (Temperature sensor; thermistor) Annex 3 (a), as documented in INS-IAQ-SOP02-RH (Relative humidity sensor; thin-film capacitive sensor) Annex 3 (a), as documented in INS-IAQ-SOP03-AM (Hot wire velocity probe) Annex 3 (b), as documented in INS-IAQ-SOP04-CO2 (Non-dispersive infrared NDIR) Annex 3 (b), as documented in INS-IAQ-SOP05-CO (Electrochemical sensor) Annex 3 (g), as documented in INS-IAQ-SOP06-RSP (Light scattering laser diode) Annex 3 (f), as documented in INS-IAQ-SOP07-O3 (Gas sensitive semiconductor sensor) Annex 3 (h), as documented in INS-IAQ-SOP08-TVOC (Photo-ionization sensor) Annex 3 (c), as documented in INS-IAQ-SOP09-RN (Electrostatic collection of alpha-emitters with spectral analysis) Annex 3 (e), as documented in INS-IAQ-SOP10-NO2(R) (Gas Sensitive Electrochemical sensor)

Annex III

List of inspection activities for which accreditation has been terminated

(Notification letter No.: HKIAS007-75; Effective Date of Termination: 28 November 2024)

Castco Testing Centre Ltd.

佳力高試驗中心有限公司

1/F, Sun Ling Plaza, 30 On Kui Street, On Lok Tsuen, Fanling, New Territories, Hong Kong

香港新界粉嶺安樂村安居街 30 號新寧中心 1 樓

Indoor Air Quality Inspection 室內空氣質素檢驗		
ITEM INSPECTED 檢驗項目	SPECIFIC PROPERTY OR CHARACTERISTIC INSPECTED 特定檢驗特性或特徵	SPECIFIC INSPECTION METHOD OR STANDARD 特定檢驗方法或標準
Accreditation of the following inspection activities has been terminated		
Indoor Air Quality (cont'd)	On-site sampling of : - Nitrogen Dioxide - Formaldehyde - Airborne Bacteria Walkthrough Inspection IAQ Compliance Assessment	A Guide on Indoor Air Quality Certification Scheme for Offices and Public Places, The Government of the HKSAR, Indoor Air Quality Management Group, September 2003 Annex 3 (e), as documented in INS-IAQ-SOP10-NO2 (Passive sampler) Annex 3 (d), as documented in INS-IAQ-SOP11-HCHO (Passive sampler) Annex 3 (i), as documented in INS-IAQ-SOP12-ABC (Single stage impactor) Clause 11 Clause 13 to Clause 28

Annex III

List of inspection activities for which accreditation has been terminated

(Notification Letter No. HKIAS007-73; Effective date of termination: 2 January 2024)

Castco Testing Centre Ltd.

佳力高試驗中心有限公司

1/F, Sun Ling Plaza, 30 On Kui Street, On Lok Tsuen, Fanling, New Territories, Hong Kong

香港新界粉嶺安樂村安居街 30 號新寧中心 1 樓

Construction Products 建築產品		
ITEM INSPECTED 檢驗項目	SPECIFIC PROPERTY OR CHARACTERISTIC INSPECTED 特定檢驗特性或特徵	SPECIFICATION, INSPECTION METHOD OR STANDARD 規範、檢驗方法或標準
Accreditation of the following inspection activities has been terminated		
Welding inspection	Inspection of welding procedure (MMAW, TIG, MIG, MAG, FCAW, SAW)	BS EN ISO 15609-1: 2004 ISO 15609-1: 2004

Annex II

List of inspection activities for which accreditation has been terminated

(Notification Letter No. HKIAS007-67; Effective date of termination: 21 June 2023)

Castco Testing Centre Ltd.

佳力高試驗中心有限公司

1/F, Sun Ling Plaza, 30 On Kui Street, On Lok Tsuen, Fanling, New Territories, Hong Kong

香港新界粉嶺安樂村安居街30號新寧中心1樓

Construction Products 建築產品		
ITEM INSPECTED 檢驗項目	SPECIFIC PROPERTY OR CHARACTERISTIC INSPECTED 特定檢驗特性或特徵	SPECIFICATION, INSPECTION METHOD OR STANDARD 規範、檢驗方法或標準
Accreditation of the following inspection activities has been terminated		
Welding inspection	Inspection of welding procedure (MMAW, TIG, MIG, MAG, FCAW, SAW) Inspection of welder testing (MMAW, TIG, MIG, MAG, FCAW, SAW) Inspection of fusing welding of steel castings (MMAW)	BS 4870: Part 1: 1981 + Amd. 6293 BS EN 288-3: 1992 + Amd. 9736 BS 4871: Part 1: 1982 + Amd. 5697 BS 4872: Part 1: 1982 + Amd. 4640 BS 4570: 1985

Annex II

List of inspection activities for which accreditation has been terminated

(Notification Letter No.: HKIAS007-54; Effective date of termination: 3 March 2021)

Castco Testing Centre Ltd.

佳力高試驗中心有限公司

6/F., Techno Centre, 33 On Kui Street, On Lok Tsuen, Fanling, New Territories, Hong Kong

香港新界粉嶺安樂村安居街 33 號得利中心 6 樓

Indoor Air Quality Inspection 室內空氣質素檢驗		
ITEM INSPECTED 檢驗項目	SPECIFIC PROPERTY OR CHARACTERISTIC INSPECTED 特定檢驗特性或特徵	SPECIFIC INSPECTION METHOD OR STANDARD 特定檢驗方法或標準
Accreditation of the following inspection activities is terminated		
Indoor Air Quality	On-site measurement of : - Formaldehyde On-site measurement of : - Formaldehyde	A Guide on Indoor Air Quality Certification Scheme for Offices and Public Places, The Government of the HKSAR, Indoor Air Quality Management Group, September 2003 Annex 3 (d), as documented in INS-IAQ-SOP11- (Photoelectric photometry detector) A Guide on Indoor Air Quality Certification Scheme for Offices and Public Places, The Government of the HKSAR, Indoor Air Quality Management Group, January 2019 Annex 4 (c), as documented in INS-IAQ-SOP11- (Photoelectric photometry detector)

Annex II

List of activities for which accreditation has been terminated

(Notification Letter No. HKIAS007-45; Effective date of termination: 12 September 2018)

Castco Testing Centre Ltd.

佳力高試驗中心有限公司

6/F., Techno Centre, 33 On Kui Street, On Lok Tsuen, Fanling, New Territories, Hong Kong

香港新界粉嶺安樂村安居街 33 號得利中心 6 樓

Indoor Air Quality Inspection 室內空氣質素檢驗		
ITEM INSPECTED 檢驗項目	SPECIFIC PROPERTY OR CHARACTERISTIC INSPECTED 特定檢驗特性或特徵	SPECIFIC INSPECTION METHOD OR STANDARD 特定檢驗方法或標準
Accreditation of the following inspection has been terminated		
Indoor Air Quality	On-site sampling of : - Airborne Bacteria	A Guide on Indoor Air Quality Certification Scheme for Offices and Public Places, The Government of the HKSAR, Indoor Air Quality Management Group, September 2003 Annex 3 (i), as documented in INS-IAQ-SOP12-ABC (centrifugal sampler)

Annex II

List of tests for which accreditation has been terminated

(Notification Letter No.: HKIAS007-43 Effective date of termination: 16 July 2018)

Castco Testing Centre Ltd.

佳力高試驗中心有限公司

6/F., Techno Centre, 33 On Kui Street, On Lok Tsuen, Fanling, New Territories, Hong Kong

香港新界粉嶺安樂村安居街 33 號得利中心 6 樓

Construction Materials 建築材料		
ITEM TESTED OR MEASURED 測試或量度項目	SPECIFIC TEST OR PROPERTY MEASURED 特定測試或量度的特性	SPECIFICATION, STANDARD METHOD OR TECHNIQUE USED 規範、標準方法或應用技術
Accreditation of the following tests has been terminated		
Paint	Inspection/approval of paint procedures	In-house Method INS-PAINTING-STEEL

Annex III

List of activities for which accreditation has been terminated

(Notification Letter No.: HKIAS007-29; Effective date of termination: 10 July 2015)

Castco Testing Centre Ltd.

佳力高試驗中心有限公司

INSPECTION FIELD 檢驗範圍	ITEM, MATERIAL OR PRODUCT TESTED 檢驗項目、物料或產品	SPECIFIC PROPERTY OR CHARACTERISTIC INSPECTED 特定檢驗特性或特徵	SPECIFIC INSPECTION METHOD OR STANDARD 特定檢驗方法或標準
CONSTRUCTION PRODUCTS INSPECTION	Precast Products - Precast Concrete Facade - Precast Staircase - Precast Concrete Pipe	Post construction dimensional inspection prior to delivery or shipment Post construction dimensional inspection prior to delivery or shipment Post construction dimensional inspection prior to delivery or shipment	HKHA Specification (2000) App. H CON 5.W410.3-5.W420.3 TOL.CON 7.010.3-7.040.3 HKHA Specification (2000) App. H CON 5.W410.3-5.W420.3 TOL.CON 4.010.3, TOL.CON 4.120.3-4.180.3 BS 5911 : Part 100 : 1998(Amd. 7588) Section 3