

Annex II

List of inspection activities for which accreditation has been terminated

(Notification letter No.: HKIAS008-70; Effective Date of Termination: 8 January 2025)

Fugro Technical Services Limited

輝固技術服務有限公司

Fugro Development Centre, 5 Lok Yi Street, Tai Lam, Tuen Mun, New Territories, Hong Kong

香港新界屯門大欖樂怡街五號輝固發展中心

| Construction Products 建築產品 | | |
|---|--|--|
| ITEM INSPECTED 檢驗項目 | SPECIFIC PROPERTY OR CHARACTERISTIC INSPECTED 特定檢驗特性或特徵 | SPECIFICATION, INSPECTION METHOD OR STANDARD 規範、檢驗方法或標準 |
| Accreditation of the following inspection activities has been terminated | | |
| Waterworks Products - Valves & fittings | Inspection of testing, dimensional check, material properties, coating, marking and handling | BS 5146: Part 2: 1984 BS 5150: 1990 BS 5153: 1974 BS 5154: 1991 BS 5155: 1984 BS 5156: 1985 Water Supplies Department Particular Specification App. 23.05 Water Supplies Department Particular Specification App. 23.11 |

Annex II

List of inspection activities for which accreditation has been terminated

(Notification letter No.: HKIAS008-69; Effective Date of Termination: 12 December 2024)

Fugro Technical Services Limited

輝固技術服務有限公司

Fugro Development Centre, 5 Lok Yi Street, Tai Lam, Tuen Mun, New Territories, Hong Kong

香港新界屯門大欖樂怡街五號輝固發展中心

| Construction Products 建築產品 | | |
|---|--|---|
| ITEM INSPECTED 檢驗項目 | SPECIFIC PROPERTY OR CHARACTERISTIC INSPECTED 特定檢驗特性或特徵 | SPECIFICATION, INSPECTION METHOD OR STANDARD 規範、檢驗方法或標準 |
| Accreditation of the following inspection activities has been terminated | | |
| Welding Inspection | Inspection of welding procedures (MMAW, TIG, MIG, MAG, FCAW, SAW) Inspection of welder testing (MMAW, TIG, MIG, MAG, FCAW, SAW) | BS 4870: Part 1: 1981 + Amd. 6293 BS EN 288-3: 1992 + Amd. 9736 + Amd. 10026 Corr. No. 1 BS EN 288-8: 1995 BS 4871: Part 1: 1982 + Amd. 5697 BS 4872: Part 1: 1982 + Amd. 4640 BS EN 287-1: 1992 + Amd. 9665 + Amd. 10009 Corr. No. 1 BS EN 287-1: 2004 |

Annex III

List of inspection activities for which accreditation has been terminated

(Notification letter No.: HKIAS008-68; Effective Date of Termination: 8 August 2024)

Fugro Technical Services Limited

輝固技術服務有限公司

Fugro Development Centre, 5 Lok Yi Street, Tai Lam, Tuen Mun, New Territories, Hong Kong

香港新界屯門大欖樂怡街五號輝固發展中心

| Indoor Air Quality Inspection 室內空氣質素檢驗 | | |
|---|---|---|
| ITEM INSPECTED 檢驗項目 | SPECIFIC PROPERTY OR CHARACTERISTIC INSPECTED 特定檢驗特性或特徵 | SPECIFIC INSPECTION METHOD OR STANDARD 特定檢驗方法或標準 |
| Accreditation of the following inspection activities has been terminated | | |
| Indoor Air Quality Inspection | On-site measurement of : - Carbon Dioxide - Respirable Suspended Particulate Walkthrough Inspection IAQ Compliance Assessment for the first to fourth annual re-certification | A Guide on Indoor Air Quality Certification Scheme for Offices and Public Places, The Government of the HKSAR, Indoor Air Quality Management Group, September 2003 Annex 3 (b), as documented in E-I-002 (non-dispersive infrared NDIR) Annex 3 (g), as documented in E-I-001 (light scattering laser diode) Clause 11 Clause 13 to Clause 28 |

Annex II

List of inspection activities for which accreditation has been terminated

(Notification letter No.: HKIAS008-63; Effective Date of Termination: 16 January 2024)

Fugro Technical Services Limited

輝固技術服務有限公司

Fugro Development Centre, 5 Lok Yi Street, Tai Lam, Tuen Mun, New Territories, Hong Kong

香港新界屯門大欖樂怡街五號輝固發展中心

| Construction Products 建築產品 | | |
|--|---|---|
| ITEM INSPECTED 檢驗項目 | SPECIFIC PROPERTY OR CHARACTERISTIC INSPECTED 特定檢驗特性或特徵 | SPECIFIC INSPECTION METHOD OR STANDARD 特定檢驗方法或標準 |
| Accreditation of the following inspection activities has been terminated. | | |
| Indoor Air Quality Inspection | On-site measurement of : - Temperature - Relative Humidity - Air Movement - Carbon Monoxide - Formaldehyde - Nitrogen Dioxide - Total Volatile Organic Compounds - Radon - Ozone On-site sampling of : - Airborne Bacteria | A Guide on Indoor Air Quality Certification Scheme for Offices and Public Places, The Government of the HKSAR, Indoor Air Quality Management Group, September 2003 Annex 3 (a), as documented in E-I-002 (temperature sensor; thermistor) Annex 3 (a), as documented in E-I-002 (humidity sensor capacitive measurement principle) Annex 3 (a), as documented in E-I-002 (hot wire velocity probe) (Passive sampler) Annex 3 (b), as documented in E-I-002 (electrochemical sensor) Annex 3 (d), as documented in E-I-011 (photoelectric photometry method) Annex 3 (e), as documented in E-I-012 (gas sensitive electrochemical sensor) Annex 3 (h), as documented in E-I-003 (photo-ionization sensor) Annex 3 (c), as documented in E-I-005 (electrostatic collection of alpha-emitters with spectral analysis) Annex 3 (f), as documented in E-I-010 (gas sensitive semiconductor sensor) Annex 3 (i), as documented in E-I-013 (single-stage impactor) |

Annex II

List of inspection activities for which accreditation has been terminated

(Notification Letter No. HKIAS008-62; Effective date of termination: 15 December 2023)

Fugro Technical Services Limited

輝固技術服務有限公司

Fugro Development Centre, 5 Lok Yi Street, Tai Lam, Tuen Mun, New Territories, N T, Hong Kong

香港新界屯門大欖樂怡街五號輝固發展中心

| Construction Products 建築產品 | | |
|---|--|---|
| ITEM INSPECTED 檢驗項目 | SPECIFIC PROPERTY OR CHARACTERISTIC INSPECTED 特定檢驗特性或特徵 | SPECIFICATION, INSPECTION METHOD OR STANDARD 規範、檢驗方法或標準 |
| The accreditation of the following inspection activity has been terminated | | |
| Welding Inspection | Inspection of welding procedures (MMAW, TIG, MIG, MAG, FCAW, SAW) | BS EN ISO 15609-1: 2004 |

Annex III

List of inspection activities for which accreditation has been terminated

(Notification letter No.: HKIAS008-61; Effective Date of Termination: 1 December 2023)

Fugro Technical Services Limited

輝固技術服務有限公司

Fugro Development Centre, 5 Lok Yi Street, Tai Lam, Tuen Mun, New Territories, Hong Kong

香港新界屯門大欖樂怡街五號輝固發展中心

| Construction Products 建築產品 | | |
|--|---|---|
| ITEM INSPECTED 檢驗項目 | SPECIFIC PROPERTY OR CHARACTERISTIC INSPECTED 特定檢驗特性或特徵 | SPECIFIC INSPECTION METHOD OR STANDARD 特定檢驗方法或標準 |
| Accreditation of the following inspection activities has been terminated. | | |
| Indoor Air Quality Inspection | On-site measurement of : - Ozone On-site sampling of : - Airborne Bacteria - Formaldehyde - Nitrogen Dioxide | A Guide on Indoor Air Quality Certification Scheme for Offices and Public Places, The Government of the HKSAR, Indoor Air Quality Management Group, September 2003 Annex 3 (f), as documented in E-I-004 (Electrochemical sensor) Annex 3 (i), as documented in E-I-006 (centrifugal sampler) Annex 3 (d), as documented in E-I-007 (Passive sampler) Annex 3 (e), as documented in E-I-008 (Passive sampler) |
| Indoor Air Quality Inspection | On-site measurement of : - Ozone On-site sampling of : - Airborne Bacteria - Formaldehyde - Nitrogen Dioxide | A Guide on Indoor Air Quality Certification Scheme for Offices and Public Places, The Government of the HKSAR, Indoor Air Quality Management Group, January 2019 Annex 4 (e), as documented in E-I-004 (Electrochemical sensor) Annex 4 (h), as documented in E-I-006 (centrifugal sampler) Annex 4 (c), as documented in E-I-007 (passive sampler) Annex 4 (d), as documented in E-I-008 (passive sampler) |

Annex II

List of inspection activities for which accreditation has been terminated
(Notification letter No.: HKIAS008-50; Effective Date of Termination: 9 April 2020)

Fugro Technical Services Limited

輝固技術服務有限公司

Fugro Development Centre, 5 Lok Yi Street, Tai Lam, Tuen Mun, New Territories, Hong Kong

香港新界屯門大欖樂怡街五號輝固發展中心

| Construction Products 建築產品 | | |
|--|---|--|
| ITEM INSPECTED 檢驗項目 | SPECIFIC PROPERTY OR CHARACTERISTIC INSPECTED 特定檢驗特性或特徵 | SPECIFIC INSPECTION METHOD OR STANDARD 特定檢驗方法或標準 |
| Accreditation of the following inspection activities has been terminated. | | |
| Waterworks Products | Inspection of testing, dimensional check, material properties, coating, marking and handling of polyethylene pipes and fittings | ISO 4427: 1996 ISO 14236: 2000 JIS K6762: 2004 Water Industry Specification WIS 4-24-01 (Jul 1998) Issue 2 Water Industry Specification WIS 4-32-14 (Mar 1995) Issue 1 Water Industry Specification WIS 4-32-15 (Mar 1995) Issue 1 Water Industry Specification WIS 4-52-01 (Dec 1992) Issue 1 Water Supplies Department Particular Specification App. 23.09 |

Annex III

List of inspections for which accreditation has been terminated

(Notification Letter No.: HKIAS008-31; Effective date of termination: 8 January 2016)

Fugro Technical Services Limited

輝固土力工程及檢測有限公司

| INSPECTION FIELD 檢驗領域 | ITEM, MATERIAL OR PRODUCT TESTED 檢驗項目、物料或產品 | SPECIFIC PROPERTY OR CHARACTERISTIC INSPECTED 特定檢驗特性或特徵 | SPECIFIC INSPECTION METHOD OR STANDARD 特定檢驗方法或標準 |
|---------------------------------|---|---|--|
| CONSTRUCTION PRODUCTS | Waterworks Products | | |
| | Steel pipes & fitting | Inspection of testing, lining, dimensional checks, material properties, coating marking and handling | WSD(PS) App. 23.02 BS 534: 1990 |
| | Ductile iron pipes & fitting | Inspection of testing, lining, dimensional checks, material properties, coating marking and handling | WSD(PS): App. 23.03 BS 4772: 1988 BS EN 545: 1995 BS EN 545: 2002 BS EN598: 1995 |
| | Cast iron pipes & fittings | Inspection of testing, lining, dimensional checks, material properties, coating, marking and handling | WSD(PS): App. 23.10 WSD(PS): App. 23.12 BS 143 & BS 1256: 2000 JIS B2301: 2004 BS EN 877: 1999 |
| | Steel pipes/tubes and fitting | Inspection of testing, lining, dimensional checks, material properties, coating, marking and handling | WSD (PS): App. 23.12 BS 1387: 1985 BS EN 10241: 2000 |

Annex III

List of activities for which accreditation has been terminated

(Effective date of termination: 27 April 2015)

Fugro Technical Services Limited

輝固土力工程及檢測有限公司

| INSPECTION FIELD 檢驗範圍 | ITEM, MATERIAL OR PRODUCT TESTED 檢驗項目、物料或產品 | SPECIFIC PROPERTY OR CHARACTERISTIC INSPECTED 特定檢驗特性或特徵 | SPECIFIC INSPECTION METHOD OR STANDARD 特定檢驗方法或標準 |
|----------------------------------|--|--|--|
| CONSTRUCTION PRODUCTS INSPECTION | Waterworks Products Manhole cover (with coating) Surface box Fire hydrants (Pedestal and swan neck) | Inspection of testing, dimensional check, material properties, coating, marking and handling Inspection of testing, dimensional check, material properties, coating, marking, and handling Inspection of testing, dimensional check material properties, coating, marking and handling | WSD(PS) App. 23.14 BS EN 124: 1994 (exclude Clause 5 and 10) WSD(PS) Appendix 23.13 BS 5834: Part 2: 1983 (exclude Clause 4) WSD (PS): Appendix 23.06 WSD (PS): App. 23.18 BS 5041-1: 1987 |