

### Annex III

#### List of inspection activities for which accreditation has been terminated

(Notification letter No.: HKIAS008-68; Effective Date of Termination: 8 August 2024)

#### **Fugro Technical Services Limited**

輝固技術服務有限公司

Fugro Development Centre, 5 Lok Yi Street, Tai Lam, Tuen Mun, New Territories, Hong Kong

香港新界屯門大欖樂怡街五號輝固發展中心

<b>Indoor Air Quality Inspection 室內空氣質素檢驗</b>		
<b>ITEM INSPECTED</b> 檢驗項目	<b>SPECIFIC PROPERTY OR CHARACTERISTIC INSPECTED</b> 特定檢驗特性或特徵	<b>SPECIFIC INSPECTION METHOD OR STANDARD</b> 特定檢驗方法或標準
<b>Accreditation of the following inspection activities has been terminated</b>		
Indoor Air Quality Inspection	On-site measurement of : - Carbon Dioxide  - Respirable Suspended Particulate  Walkthrough Inspection  IAQ Compliance Assessment for the first to fourth annual re-certification	A Guide on Indoor Air Quality Certification Scheme for Offices and Public Places, The Government of the HKSAR, Indoor Air Quality Management Group, September 2003  Annex 3 (b), as documented in E-I-002 (non-dispersive infrared NDIR)  Annex 3 (g), as documented in E-I-001 (light scattering laser diode)  Clause 11  Clause 13 to Clause 28

## Annex II

### List of inspection activities for which accreditation has been terminated

(Notification letter No.: HKIAS008-63; Effective Date of Termination: 16 January 2024)

#### Fugro Technical Services Limited

輝固技術服務有限公司

Fugro Development Centre, 5 Lok Yi Street, Tai Lam, Tuen Mun, New Territories, Hong Kong

香港新界屯門大欖樂怡街五號輝固發展中心

<b>Construction Products 建築產品</b>		
<b>ITEM INSPECTED</b> 檢驗項目	<b>SPECIFIC PROPERTY OR CHARACTERISTIC INSPECTED</b> 特定檢驗特性或特徵	<b>SPECIFIC INSPECTION METHOD OR STANDARD</b> 特定檢驗方法或標準
<b>Accreditation of the following inspection activities has been terminated.</b>		
Indoor Air Quality Inspection	On-site measurement of : - Temperature  - Relative Humidity  - Air Movement  - Carbon Monoxide  - Formaldehyde  - Nitrogen Dioxide  - Total Volatile Organic Compounds  - Radon  - Ozone  On-site sampling of : - Airborne Bacteria	A Guide on Indoor Air Quality Certification Scheme for Offices and Public Places, The Government of the HKSAR, Indoor Air Quality Management Group, September 2003  Annex 3 (a), as documented in E-I-002 (temperature sensor; thermistor)  Annex 3 (a), as documented in E-I-002 (humidity sensor capacitive measurement principle)  Annex 3 (a), as documented in E-I-002 (hot wire velocity probe) (Passive sampler)  Annex 3 (b), as documented in E-I-002 (electrochemical sensor)  Annex 3 (d), as documented in E-I-011 (photoelectric photometry method)  Annex 3 (e), as documented in E-I-012 (gas sensitive electrochemical sensor)  Annex 3 (h), as documented in E-I-003 (photo-ionization sensor)  Annex 3 (c), as documented in E-I-005 (electrostatic collection of alpha-emitters with spectral analysis)  Annex 3 (f), as documented in E-I-010 (gas sensitive semiconductor sensor)  Annex 3 (i), as documented in E-I-013 (single-stage impactor)

## Annex II

### List of inspection activities for which accreditation has been terminated

(Notification Letter No. HKIAS008-62; Effective date of termination: 15 December 2023)

#### **Fugro Technical Services Limited**

輝固技術服務有限公司

Fugro Development Centre, 5 Lok Yi Street, Tai Lam, Tuen Mun, New Territories, N T, Hong Kong

香港新界屯門大欖樂怡街五號輝固發展中心

<b>Construction Products 建築產品</b>		
ITEM INSPECTED 檢驗項目	SPECIFIC PROPERTY OR CHARACTERISTIC INSPECTED 特定檢驗特性或特徵	SPECIFICATION, INSPECTION METHOD OR STANDARD 規範、檢驗方法或標準
<b>The accreditation of the following inspection activity has been terminated</b>		
Welding Inspection	Inspection of welding procedures (MMAW, TIG, MIG, MAG, FCAW, SAW)	BS EN ISO 15609-1: 2004

### Annex III

#### List of inspection activities for which accreditation has been terminated

(Notification letter No.: HKIAS008-61; Effective Date of Termination: 1 December 2023)

#### **Fugro Technical Services Limited**

輝固技術服務有限公司

Fugro Development Centre, 5 Lok Yi Street, Tai Lam, Tuen Mun, New Territories, Hong Kong

香港新界屯門大欖樂怡街五號輝固發展中心

<b>Construction Products 建築產品</b>		
<b>ITEM INSPECTED</b> 檢驗項目	<b>SPECIFIC PROPERTY OR CHARACTERISTIC INSPECTED</b> 特定檢驗特性或特徵	<b>SPECIFIC INSPECTION METHOD OR STANDARD</b> 特定檢驗方法或標準
<b>Accreditation of the following inspection activities has been terminated.</b>		
Indoor Air Quality Inspection	On-site measurement of : - Ozone  On-site sampling of : - Airborne Bacteria  - Formaldehyde  - Nitrogen Dioxide	A Guide on Indoor Air Quality Certification Scheme for Offices and Public Places, The Government of the HKSAR, Indoor Air Quality Management Group, September 2003  Annex 3 (f), as documented in E-I-004 (Electrochemical sensor)  Annex 3 (i), as documented in E-I-006 (centrifugal sampler)  Annex 3 (d), as documented in E-I-007 (Passive sampler)  Annex 3 (e), as documented in E-I-008 (Passive sampler)
Indoor Air Quality Inspection	On-site measurement of : - Ozone  On-site sampling of : - Airborne Bacteria  - Formaldehyde  - Nitrogen Dioxide	A Guide on Indoor Air Quality Certification Scheme for Offices and Public Places, The Government of the HKSAR, Indoor Air Quality Management Group, January 2019  Annex 4 (e), as documented in E-I-004 (Electrochemical sensor)  Annex 4 (h), as documented in E-I-006 (centrifugal sampler)  Annex 4 (c), as documented in E-I-007 (passive sampler)  Annex 4 (d), as documented in E-I-008 (passive sampler)

## Annex II

List of inspection activities for which accreditation has been terminated  
(Notification letter No.: HKIAS008-50; Effective Date of Termination: 9 April 2020)

### Fugro Technical Services Limited

輝固技術服務有限公司

Fugro Development Centre, 5 Lok Yi Street, Tai Lam, Tuen Mun, New Territories, Hong Kong

香港新界屯門大欖樂怡街五號輝固發展中心

<b>Construction Products 建築產品</b>		
<b>ITEM INSPECTED</b> 檢驗項目	<b>SPECIFIC PROPERTY OR CHARACTERISTIC INSPECTED</b> 特定檢驗特性或特徵	<b>SPECIFIC INSPECTION METHOD OR STANDARD</b> 特定檢驗方法或標準
<b>Accreditation of the following inspection activities has been terminated.</b>		
Waterworks Products	Inspection of testing, dimensional check, material properties, coating, marking and handling of polyethylene pipes and fittings	ISO 4427: 1996 ISO 14236: 2000 JIS K6762: 2004 Water Industry Specification WIS 4-24-01 (Jul 1998) Issue 2 Water Industry Specification WIS 4-32-14 (Mar 1995) Issue 1 Water Industry Specification WIS 4-32-15 (Mar 1995) Issue 1 Water Industry Specification WIS 4-52-01 (Dec 1992) Issue 1 Water Supplies Department Particular Specification App. 23.09

### Annex III

#### List of inspections for which accreditation has been terminated

(Notification Letter No.: HKIAS008-31; Effective date of termination: 8 January 2016)

#### **Fugro Technical Services Limited**

輝固土力工程及檢測有限公司

<b>INSPECTION FIELD</b> 檢驗領域	<b>ITEM, MATERIAL OR PRODUCT TESTED</b> 檢驗項目、物料或產品	<b>SPECIFIC PROPERTY OR CHARACTERISTIC INSPECTED</b> 特定檢驗特性或特徵	<b>SPECIFIC INSPECTION METHOD OR STANDARD</b> 特定檢驗方法或標準
CONSTRUCTION PRODUCTS	Waterworks Products		
	Steel pipes & fitting	Inspection of testing, lining, dimensional checks, material properties, coating marking and handling	WSD(PS) App. 23.02 BS 534: 1990
	Ductile iron pipes & fitting	Inspection of testing, lining, dimensional checks, material properties, coating marking and handling	WSD(PS): App. 23.03 BS 4772: 1988 BS EN 545: 1995 BS EN 545: 2002 BS EN598: 1995
	Cast iron pipes & fittings	Inspection of testing, lining, dimensional checks, material properties, coating, marking and handling	WSD(PS): App. 23.10 WSD(PS): App. 23.12 BS 143 & BS 1256: 2000 JIS B2301: 2004 BS EN 877: 1999
	Steel pipes/tubes and fitting	Inspection of testing, lining, dimensional checks, material properties, coating, marking and handling	WSD (PS): App. 23.12 BS 1387: 1985 BS EN 10241: 2000

### Annex III

#### List of activities for which accreditation has been terminated

(Effective date of termination: 27 April 2015)

#### **Fugro Technical Services Limited**

輝固土力工程及檢測有限公司

<b>INSPECTION FIELD 檢驗範圍</b>	<b>ITEM, MATERIAL OR PRODUCT TESTED 檢驗項目、物料或產品</b>	<b>SPECIFIC PROPERTY OR CHARACTERISTIC INSPECTED 特定檢驗特性或特徵</b>	<b>SPECIFIC INSPECTION METHOD OR STANDARD 特定檢驗方法或標準</b>
CONSTRUCTION PRODUCTS INSPECTION	Waterworks Products		
	Manhole cover (with coating)	Inspection of testing, dimensional check, material properties, coating, marking and handling	WSD(PS) App. 23.14 BS EN 124: 1994 (exclude Clause 5 and 10)
	Surface box	Inspection of testing, dimensional check, material properties, coating, marking, and handling	WSD(PS) Appendix 23.13 BS 5834: Part 2: 1983 (exclude Clause 4)
	Fire hydrants (Pedestal and swan neck)	Inspection of testing, dimensional check material properties, coating, marking and handling	WSD (PS): Appendix 23.06 WSD (PS): App. 23.18 BS 5041-1: 1987