Annex III

List of tests for which accreditation has been terminated

(Notification Letter No. HOKLAS253-14; Effective date of termination: 31 January 2024)

Shenzhen Sense Engineering Services Limited

深圳市神視檢驗有限公司

Room 208, Chiwan Petroleum Building, No.6, ChiWan 5th Road, Nanshan District, Shenzhen, China 中國深圳市南山區赤灣五路六號赤灣石油大厦 208

Construction Materials 建築材料			
ITEM TESTED OR MEASURED 測試或量度項目	SPECIFIC TEST OR PROPERTY MEASURED 特定測試或量度的特性	SPECIFICATION, STANDARD METHOD OR TECHNIQUE USED 規範、標準方法或應用技術	
	The accreditation of the following test has been	terminated	
Welds (non-destructive)	Magnetic particle test (magnetic flow method, colour contrast technique using permanent magnets and A.C. yokes)	BS EN ISO 9606-1: 2017 Cl. 7 BS EN ISO 15614-1: 2017 + A1: 2019 Cl. 7.5 Level 2	
	Ultrasonic test (Butt welds in plates and pipes, 'T'-joint welds, nozzle welds and node welds)	BS EN ISO 9606-1: 2017 Cl. 7 BS EN ISO 15614-1: 2017 + A1: 2019 Cl. 7.5 Level 2	
	Visual examination	BS EN ISO 9606-1: 2017 Cl. 7 BS EN ISO 15614-1: 2017 + A1: 2019 Cl. 7.5 Level 2	

Annex II

List of tests for which accreditation has been terminated

(Notification Letter No. HOKLAS253-8; Effective date of termination: 11 June 2019)

Shenzhen Sense Engineering Services Limited

深圳市神視檢驗有限公司

A Unit, D Area, 3/F, Haihui Building, Nanyou Road, Nanshan District, Shenzhen City, China 深圳市南山區南油大道海暉大厦裙樓 3 樓 D 區 A 單位

Construction Materials 建築材料			
ITEM TESTED OR MEASURED 測試或量度項目	SPECIFIC TEST OR PROPERTY MEASURED 特定測試或量度的特性	SPECIFICATION, STANDARD METHOD OR TECHNIQUE USED 規範、標準方法或應用技術	
	The accreditation of the following test has been	n terminated	
Welds (non-destructive)	Ultrasonic test	BS EN ISO 17640: 2017 (Butt welds in plates and pipes, 'T'-joint, nozzle welds and node welds)	