

Annex III

List of tests for which accreditation has been terminated

(Notification Letter No. HOKLAS264-12; Effective date of termination: 1 March 2024)

Soil Services Testing Company Limited

土質試驗有限公司

Units 03, 04 & 10, 13/F, Luen Cheong Can Centre, 8 Yip Wong Road, Tuen Mun, New Territories, Hong Kong

香港新界屯門業旺路8號聯昌中心13樓03室、04室和10室

Construction Materials 建築材料		
ITEM TESTED OR MEASURED 測試或量度項目	SPECIFIC TEST OR PROPERTY MEASURED 特定測試或量度的特性	SPECIFICATION, STANDARD METHOD OR TECHNIQUE USED 規範、標準方法或應用技術
Accreditation of the following tests has been terminated		
Foundation	Plate load test (PLT)	BS 1377: Part 9: 1990 + Amd 8264 Cl. 4.1 (incremental loading) Buildings Department Code of Practice for Foundations (Oct 2004) Cl. 8.2 excluding 8.2(e) Buildings Department Code of Practice for Foundations (Apr 2017) Cl. 8.2(2) excluding 8.2(2)(f) to (h)
Soil (Phase II)	Unconfined compressive strength of cohesive soil by load frame method	BS EN ISO 17892-7: 2018